


Community Advisory

South Van Buren Street

Sanitary Sewer Rehabilitation

- Project Description:** Work is continuing to design the rehabilitation of the sanitary sewers located in the 100 block of South Van Buren Street. In order to complete this analysis, additional tree survey information is needed. **On Sept. 5, 2013, the City's consultant, Gannett Fleming, Inc., performed field work to identify the existing trees' species, size and health in the surrounding area.** The survey limits include the rear and side yards of the properties along the east side of Evans Street, between 112 and 124 Evans St., as well as the rear yards of the properties on the west side of South Van Buren Street, between 121 and 139 South Van Buren St. Tree survey personnel accessed your property to collect this information.
- Purpose:** Rehabilitation of damaged sanitary sewer mains
- Location:** Behind the homes on the western side of the 100 block of South Van Buren Street and the eastern side of the 100 block of Evans Street
- Timeline:** Tree Survey work was performed during normal business hours on Sept. 5, 2013. **A community meeting is scheduled for Thursday, Sept. 12 at 6 p.m. in front of 135 South Van Buren Street to discuss the proposed alternatives for the sanitary sewer rehabilitation.** Construction is anticipated to begin spring 2014.
- Cost:** Design: \$81,489. Once the design is complete, additional information will be provided regarding the cost of the rehabilitation.
- Contact:** Jim Woods, Rockville Project Manager, 240-314-8521 or jwoods@rockvillemd.gov
Rocio Snowdy, Rockville Neighborhood Resources Coordinator, at 240-314-8345 or rsnowdy@rockvillemd.gov





Sanitary Sewer

- Manholes
- Cleanouts
- Pipes
- Laterals
- - - House connections